

# Oil Field Environmental Incident Summary

**Incident:** 20141121101606      **Date/Time of Notice:** 11/21/2014 10:16

**Responsible Party:** Triangle USA Petroleum Corporation

**Well Operator:** TRIANGLE USA PETROLEUM CORPORATION

**Well Name:** MONSON CTB

**Field Name:** ELK

**Well File #:**

**Date Incident:** 11/19/2014      **Time Incident:** 07:00      **Facility ID Number:** 223975-01

**County:** MCKENZIE      **Twp:** 152      **Rng:** 102      **Sec:** 35      **Qtr:** SE SW

**Location Description:** Central Tank Battery for the Monson 152-102-35-26-(1-4)H, Well file #'s 23975, 27379, 27378, 27377 and surrounding off-site area including barrow ditches.

**Submitted By:** Brittany Vannoy

**Received By:**

**Contact Person:** Brittany Vannoy  
1200 17TH ST., SUITE 2600  
DENVER, CO 80202-5826

**General Land Use:** Well/Facility Site

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Other

**Release Contained in Dike:** No

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	5	Barrels				

Brine

Other

**Description of Other Released Contaminant:**

**Inspected:**      **Written Report Received:** 2/11/2015      **Clean Up Concluded:** 11/26/2014

**Risk Evaluation:**

No immediate health hazard.

**Areal Extent:**

It is estimated that 168 yards of topsoil have been impacted, on and off location.

**Potential Environmental Impacts:**

The soil has been contaminated with crude, booms have been put in place to contain any hydrocarbon run-off while temperatures rise through-out the day.

**Action Taken or Planned:**

TUSA has contacted both landowners on the north and south of the road. The land owner to the south does not want any clean-up to happen in his field however the borrow ditch will be cleaned. TUSA has employed Absorbent & Safety Solutions to clean and remediate spill. Spill clean-up will commence immediately after one-call has come through. Immediate precautions have been taken to reduce hydrocarbon run-off from snow melt. The pump house will be pressure washed, impacted material will be scraped and replaced with topsoil.

**Wastes Disposal Location:** Indian Hills Disposal, pre-paperwork has already been completed.

**Agencies Involved:****Updates**

---

**Date:** 11/21/2014 **Status:** Reviewed - Follow-up Required

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to other causes, got off location. Followup is necessary.

---

**Date:** 11/25/2014 **Status:** Inspection

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Company personnel took me to the site. I arrived to the site at 3:01 p.m. The weather was 34°F and snowing, with the wind from the northwest at 15 mph. There were a couple of inches of snow on the ground. The road going into the site sits higher than the pad. The mist went southwest, hitting the sidewall of the road and into a stubble field just south of well. The area on the road has been cleaned up. Company is working with the landowner on the south side of site. Awaiting documentation. Further follow-up needed. 47 56.171; -103 42.418

---

**Date:** 2/6/2015    **Status:** Correspondence

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Received landowner documentation.

---

**Date:** 2/6/2015    **Status:** Correspondence

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Will be sending in documentation.